

Date of Bid Walk: 4/5/18 Due Date	e: 4/12/18 HNS#:		•
•	lress 📗	PBE Amount	
PUBLIC BODY ESTIMATE 2000	PWEW	19,500	
PUBLIC BODY ESTIMATE:			
PUBLIC BODY ESTIMATE:		4.15 22,425	(2.925
PUBLIC BODY ESTIMATE:		+.15 22,425 15 1/2,575	
PUBLIC BODY ESTIMATE:			·
	BID WALK ATTENDEES	3	•
JUSPEV EN.			
Jasper Env. Touch Construction			
	•		
	·		,
	Touch	BIDDERS	
Address	2000 ·	Dasper	
Address:		15,495	/
1 <u>2000 Purser</u>	24,810	1121713 / 100	D
2.	· 		
-		MPILI	8/10
3		X X X X X X X X X X X X X X X X X X X	
4.			
5.			
· · · · · · · · · · · · · · · · · · ·		•	
This is to certify that bids for the job identifie			9 Dusings Carvings
Office located at 600 E. Trade Street, Charlot		a and read aloud in the Neighborhood	& Business services
		ed By: (Imandel	2000
Bids Opened By:	Bids Record		2000(
Witnessed By:	Date:	41218	
	l within a range of 15% above	and 15% below the public body cost e	stimate. As a

Address Date

Internal COST ESTIMATE 2000 Purser Dr.

COST Per Number Unit

	H		
			13 Additional Clearance(s) Optional
		clean floor and paint with a weather resistant, outdoor, epoxy non-slip floor paint	12 EXTERIOR-Side A Porch concrete floor
		Replace any Side C components on the rear of dwelling at Room 7 Mud Room which were removed / damaged during room removal (Feature #1 Interior) Prime / paint to match any replaced wood products.	EXTERIOR -Side C- Replacement of components
		Replace decayed woaod. Re-fasten any loose wood. Scrape loose paint and re-paint.	EXTERIOR - Side A thru Side D- white wood fasclas, soffits, crown moldings, trim boards, attic air vents and frames (Note: It appearas some of these components on 10 the Side A porch have been replaced)
		Remove entire Room and components (see Item #1-Interior)	Room 7)- light brown and brown wood 9 walls and comer board
		Remove door components and replace with pre-hung steel door	wood door, casings, headers, I jambs and stops EXTERIOR Side B the Side D (a. 157)
.		Remove	EXTERIOR - Side B and Side C - white 7 wood fence pieces along the ground
		Replace wood windows with vinyl double-hung windows, cover window casings, headers and sills with Tyvek and aluminum coil stock.	wood windows, casings, headers, sills, sashes and wells (Note: Window A1 and Window A2 sashes and wells have been 6 replaced with aluminum windows
		Per Risk Assesment - Remvoe soil and replace with mulch	EXTERIOR - Side A thru Side D - paint 5 chips along drip-line
		Clean all interior components (see Risk Assesment for details)	INTERIOR - Elevated dust levels 4 throughout
		All intelior floor coverings to be cleaned. Bath floor coverings are finished. Finish-sand kitchen hardwoods, stain per owners choice and apply finish coat. Finish coat on all remaining hardwood floor coverings.	3 INTERIOR - Floor Coverings
		Remove (see feature #1) and replace with pre-hung steel door.	INTERIOR Door C1- (to Room 7) white wood door casings, headers, jambs and 2 stops (no door)
		Remove entire from and components. See Lead Report. Clean floor and then paint with weather resistant, outdoor epoxy non-slip floor paint.	1 INTERIOR - Room 7, Mud Room
Cost Per Unit	Cost Number Unit		Item# Feature
1800			

Total Cost Estimate

Enter Item In box 85; and scope for that Item In CS...Items will copy Into the Bid Sheet.
When printing; the Budget Sheet, allow Fit Sheet on one page as below

	Normal Margins Left: 0.7" Right: 0.7"	Letter (8.5" x 11") 8.5" x 11"	Portrait Orientation	No Staples	管间 Collated 1,2,3 1,2,3 1,2,3	Print on Both Sides Flip pages on long edge	t) to	Print Active Sheets Only print the active sheets	sectings
Fit Sheet on One Page	4	4		•					

Selective Rehab Team/Forms/Bld Forms/Led Bid Scope/Blank Jlm Rôy Bid Sheet






2000 Purser Drive

Charlotte, NC 28215

SIDE C



SIDE D

SIDE A

Legend

= Window

= Soil Sample Location

NOT TO SCALE